DMV Lane Technician Observation Report

DMV Technician: Ray Struson Position	IV Technician: Rnl) Struson Position: 1 or 2		
Station: Date: 9-30 Time	1	200	-
Vehicle Make: Chrylin Model Py anse	Year	2	
GVWR: Fuel Type: Registration Number: PC 20015			
Auditor: Coverdaly Covert Over	t (circle	one)	10013
	YES	NO	N/A
1. Did technician check vehicle paper work and verify VIN number?	2		
2. Was Emissions testing required?	1		
a) Was Emissions testing performed using OBD?	1		
b) Was Emissions testing performed using Analyzer Probe?			
c) Was Emissions testing performed using Paddle(s)?			
d) Was Emissions testing performed using Clip?			
3. Was Catalytic Converter inspection required?			V
a) Was Catalytic Converter inspection performed?			
4. Was Fuel Tank pressure testing required?			11
a) Was Fuel Tank pressure testing performed?		+	
5. Was Fuel Cap pressure testing required?			
a) Was Fuel Cap pressure testing performed?			
6. Is this test a Re-check from a prior failure?			1/
a) Which re-check test is being performed? 1 2 3 (circle one)			
b) If this is re-check #3, was repair paperwork verified for waiver?			
New Castle and Kent Counties Only			
7. Was Two-Speed Idle testing required?		1/	
a) Was Two-Speed Idle testing performed?			
Sussex County Only			
8. Was Curb Idle testing required?			
a) Was Curb Idle testing performed?			
Comment:			
Lane Supervisor Signature:			

Revised 04/12/2013